

An EEO Employer

Safety Flash

Incident with Recordable Injury

Date of Incident: 8/28/2024

The Incident

An associate was attempting to move a recently sheared sheet of expanded metal onto a pallet. As the associate was setting the piece down, a corner of the sheet caught his arm causing a 4-inch laceration which required OSHA recordable medical attention.

The Causes

- Inadequate work space was available to properly space the shearing machine, material and pallets away from each other, which hampered the associates ability to perform the work safely.
- STAC card was not filled out to remind associate that the task at hand was potentially dangerous.
- Kevlar sleeves could have been worn to help prevent such an instance from happening.

Prevent It

- Assure the layout of the workspace is adequate in the future.
- Utilize Kevlar sleeves in the immediate future.
- Fill out STAC cards to remind yourself of the task at hand for the day and what safety precautions need to be utilized

Action Plan

- Ordering Kevlar sleeves in multiple sizes to accommodate each associate in the shop.
- Schedule bi-weekly stand downs with associates in the shop and safety department to discuss different ways to combat situations like this to prevent injuries from occuring in the future.

Keep Improving

Your health and safety are the most important part of every project. We need *your* help to eliminate unsafe behaviors and conditions. If you see a safer and better way to do a task, see your supervisor, or contact GEM Safety: Bill Cornett – 419-720-2728. To get personal protection equipment from the warehouse, call 419-720-2688.

419.666.6554 6842 COMMODORE DRIVE WALBRIDGE, OH 43465 RLGBUILDS.COM